



Let's Solve Water

Xylem operates under  
the brands of YSI,  
SonTek,  
Aanderaa,  
MLK, and  
HYPACK.

YSI Incorporated  
1700/1725 Brannum Lane  
Yellow Springs, OH 45387  
USA  
tel: 937-767-7241  
fax: 937-767-9320

## Packing List

Page 1 of 10

Delivery Number	Packing Slip Number	Date Shipped
1597303	YSI-429681	10-MAR-16
Shipped Via: FEDEX-Air-FedEx 2nd Day		

## CERTIFICATE OF COMPLIANCE

This is to certify that the materials, processes and finished products were controlled, tested, and accepted in accordance with our quality system and the applicable specifications.

Ron Geis  
Vice President & General Manager

## SOLD TO

NATIONAL PARK SERVICE  
3100 NATIONAL PARK RD  
JUNEAU, AK 99801, United States

## SHIP TO

NATIONAL PARK SERVICE  
3100 NATIONAL PARK RD  
JUNEAU, AK 99801, United States

PICKUP DATE	PAYMENT TERMS	FREIGHT TERMS	SR NUMBER	INCOTERMS	TAX NAME	TAX NO.	Supplier No.
10-MAR-16	Credit Card	Prepaid	318224	2010 FCA - ORIGIN	Exempt		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO./Country of Origin	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
10.1	R6136	665100		CREDITC ARD		Repair, Model 6136 LOT#:10C101562*  6136 TURBIDITY PROBE SN#10C101562  REPORTED SYMPTOM: EVALUATION/PREVENTIVE MAINTENANCE  TESTED AND CALIBRATED PROBE ALL UPDATES IN PLACE REPLACED QUAD SEAL. REPLACED O-RINGS.  TEST WIPER FUNCTION, NO	9801.10.0000	EA	1	1	0

-For terms and conditions refer to [www.ysi.com/terms\\_conditions](http://www.ysi.com/terms_conditions)

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.



Xylem operates under the brands of YSI, SorTek, Aanderaa, MJK, and HYPACK.

YSI Incorporated  
1700/1725 Brannum Lane  
Yellow Springs, OH 45387  
USA  
tel: 937-767-7241  
fax: 937-767-9320

## Packing List

Page 2 of 10

Delivery Number	Packing Slip Number	Date Shipped
1597303	YSI-429681	10-MAR-16
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO./ Country of Origin	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
12.1	R6920V2	665100		CREDITC ARD		DEFECT FOUND. PROBE READS: 142 NTU IN 126 NTU STANDARD CALIBRATED TO 126.  FINAL TEST, MEETS YSI SPECIFICATIONS. Repair Model 6920V2 LOT# 08h100354*  MODEL#6920V2 SN#08H100354 ID: NPS-SITK  REPORTED SYMPTOM: EVALUATION/PREVENTIVE MAINTENANCE  +++++ SUMMARY: BATTERY LEAKAGE. CLEANED WITH VINEGAR. 14F PH PROBE OUT OF RANGE.  - REPLACED PH PROBE LOT#16B +++++  TEST CIRCUIT BOARD, NO DEFECT FOUND. TEST RTC BATTERY, NO DEFECT FOUND. FIRMWARE UP TO DATE AT 3.10. PERFORM CURRENT DRAW TEST. PASSED SLEEP, IDLE AND RUN MODE TESTING. TESTED WITH BATTERIES AND POWER SUPPLY.	9801.10.0000 United States	EA	1	1	0

-For terms and conditions refer to [www.ysi.com/terms\\_conditions](http://www.ysi.com/terms_conditions)  
-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.



Xylem operates under the brands of YSI, SonTek, Aanderaa, MJK, and HYPACK.

YSI Incorporated  
1700/1725 Bannum Lane  
Yellow Springs, OH 45387  
USA  
tel: 937-767-7241  
fax: 937-767-9320

## Packing List

Page 3 of 10

Delivery Number	Packing Slip Number	Date Shipped
1597303	YSI-429681	10-MAR-16
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO./ Country of Origin	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						TEST BULKHEAD FOR STRIPPED PORTS AND HIGH IMPEDANCE LEAKAGE. NO DEFECT FOUND. TEST BCR CONNECTOR AND BATTERY COMPARTMENT. NO DEFECT FOUND.					
						TEST CONDUCTIVITY/TEMPERATURE PROBE(SN#13A100451) TEMPERATURE READS 22.03°C IN A 22.0°C BATH WITH A CELL CONSTANT OF 4.99596 PROBE READS ZERO SPCOND IN AIR.					
						TEST PH PROBE(SN#16B) NO DEFECT FOUND. READINGS BELOW: 7: -0.7mV 10: -177.9mV 4: 172.7mV 177.2mV SLOPE:					
						ALL PORTS TEST = FUNCTIONAL. REPLACED O-RINGS. FINAL TEST. MEETS YSI SPECIFICATIONS. Repair, Model 6150					
14.1	R6150	665100		CREDITC ARD		6150 ROX ODO PROBE SN#11E101714	9801.10.0000	EA	1	1	0
						REPORTED SYMPTOM: EVALUATION/PREVENTIVE MAINTENANCE					

-For terms and conditions refer to [www.ysi.com/terms\\_conditions](http://www.ysi.com/terms_conditions)  
-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.







Xylem operates under the brands of YSI, SonTek, Aanderaa, MJK, and HYPACK

YSI Incorporated  
1700/1725 Brannum Lane  
Yellow Springs, OH 45387  
USA  
tel: 937-767-7241  
fax: 937-767-9320

Packing List

Page 4 of 10

Delivery Number	Packing Slip Number	Date Shipped
1597303	YSI-429681	10-MAR-16
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO./ Country of Origin	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						+++++ YSI RECOMMENDS CHANGING ROX DO MEMBRANE EVERY 12MOS TO ENSURE OPTIMAL OPERATION +++++ REPLACED MEMBRANE WITH PART#606155, LOT#16B100320  TESTED AND CALIBRATED PROBE. ALL UPDATES IN PLACE REPLACED QUAD SEAL. REPLACED O-RINGS.  TEST WIPER FUNCTION, NO DEFECT FOUND. PROBE READS 92.4% IN AERATED WATER, CALIBRATED TO 100% GAIN: 1.08188 PROBE READS .7% IN ZERO OXYGEN ENVIRONMENT.  FINAL TEST, MEETS YSI SPECIFICATIONS.  Repair Model 6920V2 LOT#08H100353*  MODEL#6920V2 SN#08H100353 NPS-GLBA  REPORTED SYMPTOM: EVALUATION/PREVENTIVE MAINTENANCE					
2.1	R6920V2	665100		CREDITC ARD			9801,10,0000 United States	EA	1	1	0

-For terms and conditions refer to [www.ysi.com/terms\\_conditions](http://www.ysi.com/terms_conditions)  
-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.



Xylem operates under the brands of YSI, SonTek, Aanderaa, MLK, and HYPACK.

YSI Incorporated  
1700/1725 Brannum Lane  
Yellow Springs, OH 45387  
USA  
tel: 937.767.7241  
fax: 937.767.9320

## Packing List

Page 5 of 10

Delivery Number	Packing Slip Number	Date Shipped
1597303	YSI-429681	10-MAR-16
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO./Country of Origin	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
<p>+++++</p> <p>SUMMARY: BATTERIES LEAKED, CLEANED COMPARTMENT WITH VINEGAR. CT PROBE HAS ELECTRODE CROSS-TALK LEAKAGE. 15A pH PROBE OUT OF RANGE, UNABLE TO CLEAN FILM OFF BULB.</p> <p>- REPLACED CT PROBE LOT#16A100578 - REPLACED pH PROBE LOT#16B +++++</p> <p>TEST CIRCUIT BOARD, NO DEFECT FOUND. TEST RTC BATTERY, NO DEFECT FOUND. FIRMWARE UP TO DATE AT 3.10. PERFORM CURRENT DRAW TEST. PASSED SLEEP, IDLE AND RUN MODE TESTING. TESTED WITH BATTERIES AND POWER SUPPLY.</p> <p>TEST BULKHEAD FOR STRIPPED PORTS AND HIGH IMPEDANCE LEAKAGE. NO DEFECT FOUND. TEST BCR CONNECTOR AND BATTERY COMPARTMENT. NO DEFECT FOUND.</p> <p>TEST CONDUCTIVITY/TEMPERATURE PROBE(SN#16A100578) TEMPERATURE READS 22.1 °C</p>											

-For terms and conditions refer to [www.ysi.com/terms\\_conditions](http://www.ysi.com/terms_conditions)  
-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.



Xylem operates under the brands of YSI, SonTek, Aanderaa, MJK, and HYPACK.

YSI Incorporated  
1700/1725 Brannum Lane  
Yellow Springs, OH 45387  
USA  
tel: 937-767-7241  
fax: 937-767-7320

## Packing List

Page 6 of 10

Delivery Number	Packing Slip Number	Date Shipped
1597303	YSI-429681	10-MAR-16
Shipped Via: FEDEX-Air-Fedex 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO./ Country of Origin	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
4.1	R6150	665100		CREDITC ARD		IN A 22.0°C BATH WITH A CELL CONSTANT OF 4.88833 PROBE READS ZERO SPCOND IN AIR.  TEST PH PROBE(SN#16B) NO DEFECT FOUND. READINGS BELOW: 7: .5mV 10: -177mV 4: 173.7mV 177.5mV  SLOPE:  ALL PORTS TEST = FUNCTIONAL.  REPLACED O-RINGS.  FINAL TEST. MEETS YSI SPECIFICATIONS.  Repair, Model 6150  6150 ROX ODO PROBE SN#08H101103  REPORTED SYMPTOM: EVALUATION/PREVENTIVE MAINTENANCE  ++++ ++++ YSI RECOMMENDS CHANGING ROX DO MEMBRANE EVERY 12MOS TO ENSURE OPTIMAL OPERATION ++++ ++++  REPLACED MEMBRANE WITH PART#606155, LOT#16B100320	9801.10.0000	EA	1	1	0

-For terms and conditions refer to [www.ysi.com/terms\\_conditions](http://www.ysi.com/terms_conditions)  
-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.





## Packing List

Page 7 of 10

Delivery Number	Packing Slip Number	Date Shipped
1597303	YSI-429681	10-MAR-16
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO./ Country of Origin	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
6.1	R6920V2	665100		CREDITC ARD		TESTED AND CALIBRATED PROBE. ALL UPDATES IN PLACE REPLACED QUAD SEAL. REPLACED O-RINGS.  TEST WIPER FUNCTION, NO DEFECT FOUND. PROBE READS 88.6% IN AERATED WATER. CALIBRATED TO 100% GAIN: 1.1286 PROBE READS 1.4% IN ZERO OXYGEN ENVIRONMENT.  FINAL TEST. MEETS YSI SPECIFICATIONS.  Repair, Model 6920V2 LOT # 08H100355*  MODEL #6920V2 SN#08H100355 ID: NPS-KLGO  REPORTED SYMPTOM: EVALUATION/PREVENTIVE MAINTENANCE  +++++ SUMMARY: CT PROBE HAS ELECTRODE CROSS-TALK LEAKAGE. YSI RECOMMENDS CHANGING PH PROBES EVERY 12MOS.  - REPLACED CT PROBE LOT #16A100678 +++++	9801.10.0000 United States	EA	1	1	0

-For terms and conditions refer to [www.ysi.com/terms\\_conditions](http://www.ysi.com/terms_conditions)  
-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.



Xylem operates under the brands of YSI, SonTek, Aanderaa, MJK, and HYPACK.

YSI Incorporated  
1700/1725 Briarum Lane  
Yellow Springs, OH 45387  
USA  
tel: 937-767-7241  
fax: 937-767-9320

## Packing List

Page 8 of 10

Delivery Number	Packing Slip Number	Date Shipped
1597303	YSI-429681	10-MAR-16
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO./ Country of Origin	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
+++++											
						TEST CIRCUIT BOARD, NO DEFECT FOUND.					
						TEST RTC BATTERY, NO DEFECT FOUND.					
						FIRMWARE UP TO DATE AT 3.10.					
						PERFORM CURRENT DRAW TEST, PASSED SLEEP, IDLE AND RUN MODE TESTING.					
						TESTED WITH BATTERIES AND POWER SUPPLY.					
						TEST BULKHEAD FOR STRIPPED PORTS AND HIGH IMPEDANCE LEAKAGE. NO DEFECT FOUND.					
						TEST BCR CONNECTOR AND BATTERY COMPARTMENT. NO DEFECT FOUND.					
						TEST					
						CONDUCTIVITY/TEMPERATURE PROBE(SN#16A100578)					
						TEMPERATURE READS 21.99°C IN A 22.0°C BATH WITH A CELL CONSTANT OF 5.03977 PROBE READS ZERO SPCOND IN AIR.					
						TEST PH PROBE(SN#14A) NO DEFECT FOUND. READINGS BELOW:					
						7: -17.8mV					
						10: -193.2mV					
						4: 157.8mV					
						175.4mV					
						SLOPE:					
						ALL PORTS TEST = FUNCTIONAL.					

-For terms and conditions refer to [www.ysi.com/terms\\_conditions](http://www.ysi.com/terms_conditions)  
-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.





Xylem operates under the brands of YSI, SonTek, Aanderaa, MJK, and HYPACK.

YSI Incorporated  
1700/1725 Brannum Lane  
Yellow Springs, OH 45387  
USA  
tel: 937-767-7241  
fax: 937-767-9320

## Packing List

Page 9 of 10

Delivery Number	Packing Slip Number	Date Shipped
1597303	YSI-429681	10-MAR-16
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO./ Country of Origin	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
8.1	R6150	665100		CREDITC ARD		REPLACED O-RINGS.  FINAL TEST. MEETS YSI SPECIFICATIONS. Repair, Model 6150	9801.10.0000	EA	1	1	0
6150 ROX ODO PROBE SN#10H101536  REPORTED SYMPTOM: EVALUATION/PREVENTIVE MAINTENANCE  ++++++ YSI RECOMMENDS CHANGING ROX DO MEMBRANE EVERY 12MOS TO ENSURE OPTIMAL OPERATION ++++++ REPLACED MEMBRANE WITH PART#606155, LOT#16B100320  TESTED AND CALIBRATED PROBE. ALL UPDATES IN PLACE REPLACED QUAD SEAL. REPLACED O-RINGS.  TEST WIPER FUNCTION, NO DEFECT FOUND. PROBE READS 91% IN AERATED WATER. CALIBRATED TO 100% GAIN: 1.09845 PROBE READS 0% IN ZERO OXYGEN ENVIRONMENT.											

-For terms and conditions refer to [www.ysi.com/terms\\_conditions](http://www.ysi.com/terms_conditions)

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.





Let's Solve Water

Xylem operates under  
the brands of YSI,  
SorTek,  
Aanderaa,  
MJK, and  
HYPACK.

YSI Incorporated  
1700/1725 Blannum Lane  
Yellow Springs, OH 45387  
USA  
tel: 937-767-7241  
fax: 937-767-9320


## Packing List

Page 10 of 10

Delivery Number	Packing Slip Number	Date Shipped
1597303	YSI-429681	10-MAR-16
Shipped Via: FEDEX-Air-FedEx 2nd Day		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO./ Country Of Origin	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
FINAL TEST. MEETS YSI SPECIFICATIONS.											
GROSS WEIGHT(LB) :		16.55	NET WEIGHT (LB) :		16.55	VOLUME(CC) :		0	TOTAL CARTONS:0		
ADDITIONAL INFO: 668944502470											
ADDITIONAL NOTE: Shipping Note: Invoice Note:											

Tracking Number:



-For terms and conditions refer to [www.ysi.com/terms\\_conditions](http://www.ysi.com/terms_conditions)

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.

